

| LOT# | Year | Make | Model | Description | Last 6 digits of VIN # | Complete VIN# | Color | Mileage | Hours | Condition |
|------|------|--------|-----------|---|------------------------|-------------------|--------|---------|-------|---|
| 1 | 2019 | Toyota | Rav4 | AWD Hybrid AC Auto Trans 2.5L 4 Cyl Gas Tire size 225-65-17 | 040395 | 2T3LWRFV3KW040395 | White | 110,725 | | Average - Mechanical: Vermont state inspection expires Oct 2024. tires are winters with about 75% tread remaining, service hybrid system light illuminated with CEL also, dealer has diagnosed it needing \$4,000 + repair, however the hybrid repair part that is needed is on national back order with no known expected time of arrival, one owner vehicle purchased new, selling due to repair costs and part not available. Body: minor scratches and dings may be found throughout. Interior: Interior is dirty and in need of cleaning. |
| 2 | 2014 | Subaru | Impreza | AWD AC Auto Trans 2.0L 4 Cyl Gas Tire size 205/55 R16 | 023568 | JF1GJAB60EH023568 | Silver | 103,901 | | Average - Mechanical: Vermont state inspection expires Aug 2024, had to jump start tires are winters with about 50% remaining, last user reported no other known issues or defects, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: lower front bumper cracked/damaged, cracked windshield, rust on right front fender, rust bubbles on rocker panels, minor scratches and dings may be found throughout. Interior: Interior is slightly dirty - license plates are missing, cannot attempt to get it inspected |
| 3 | 2014 | Ford | Focus | FWD AC Auto Trans 2.5L 4 Cyl Gas Tire size 215-55-16 | 336730 | 1FADP3F21EL336730 | Grey | 76,006 | | Average - Mechanical: Vermont state inspection expired Mar 2024. tires are winters with about 50% tread remaining, last user reported no known mechanical issues. Body: Rust starting to come through on rear lower quarter panel, may not pass VSI without future body work in this visible area, minor scratches and dings may be found throughout. Interior: Interior headliner is stained from being exposed to a leaking water, large portion of headliner is stained from water damage is likely to have more damage under the headliner not visible from the interior, Interior is dirty and in need of cleaning. Interior has mice habitation evidence, water exposure smells on interior. |
| 4 | 2013 | Subaru | Legacy | AWD AC Auto Trans 2.5L 4 Cyl Gas Tire size 205-60-16 | 044504 | 4S3BMBA64D3044504 | Blue | 94,378 | | Rough - Mechanical: Vermont state inspection expires Feb 2025. tires are winters with about 50% tread remaining, last user reported no known issues or defects, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: vehicle totaled, accident damaged to left rear door and quarter panel, minor scratches and dings may be found throughout. Interior: Interior is dirty and in need of cleaning. |
| 5 | 2012 | Chevy | Impala LS | FWD AC Auto Trans 3.6L V6 Cyl Gas Tire size 225-65-16 | 217502 | 2G1WF5E38C1217502 | Silver | 90,201 | | Rough - Mechanical: Vermont state inspection expired March 2023, exhaust leak, brakes rusty from sitting, will not pass VSI without rust repair, vehicle has been sitting for a few months in preparation for sale, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: rust repair needed underneath vehicle to pass VSI, minor scratches and dings may be found throughout. Interior: Interior is clean |
| 6 | 2015 | Subaru | Impreza | AWD AC Auto Trans 2.0L 4 Cyl Gas Tire size 195/65 R15 | 212293 | JF1GPAA6XF8212293 | Silver | 91,123 | | Average - Mechanical: Vermont state inspection expired Oct 2023, had to jump start tires are winters with about 50% remaining, TPMS light on, last user reported no known issues or defects, vehicle has been sitting for a few months in preparation for sale, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: Front lower bumper scrapes/damage, drivers and passenger rockers have dents in them, paint peeling/rust, Interior: Interior is dirty Missing license plates, cannot attempt to get inspected |
| 7 | 2014 | Ford | Fusion | Sedan - 4DR, 3.6L 6 Cyl, Automatic, Power windows and door | 179335 | 3FA6P0G75ER179335 | White | 136,360 | | Flex pipe, molding rusted rockers, Body is rust and pain chips, Interior is dirty |
| 8 | | | | Delta Model 10 tilting arbor saw SN 87K69553 | | | | | | |
| 9 | | | | (5) Welding/torch fuel carrying carts | | | Green | | | |
| 10 | | | | Craftsman radial arm saw | | | | | | |
| 11 | 1985 | Dayton | 3WO13D | Dayton Professional Industrial Power Plant Generator for electric equipment, Kawasaki FA210D engine | | 36408 N84 | Yellow | | | Pretty old, may not run |

| LOT# | Year | Make | Model | Description | Last 6 digits of VIN # | Complete VIN# | Color | Mileage | Hours | Condition |
|------|------|-------------------|--------------------------|---|------------------------|-------------------|------------------|---------|-------|---|
| 12 | | Champion | 42432 | Champion Global Power Equipment multi purpose generator, 60 Hz frequency, 120 AC volts, 1400 rate watts, 1800 starting watts | | | Yellow and black | | | Works well, pretty new |
| 13 | | Unknown | | Semi trash pump, 2x2 inch pipe size, 3.5HP honda engine | | | Red and orange | | | Quite old, unsure if starts |
| 14 | | Homelite | LR4400 | Homelite/Briggs&Stratton 4400W generator, 60Hz, 8HP engine, 120/240V | | HT3141017 | Black | | | Starts and works well, not very old |
| 15 | | Briggs & Stratton | 8HP | Briggs & Stratton 8HP Magnetron generator | | | Green | | | Starts but carburetor leaks gas |
| 16 | | | | Assorted power tools including: Craftsman 8 1/4" compund miter saw (electric) / Makita BTD141 impact driver (battery) / Makita XRJ03 18V saw zall (battery) / Black and Decker 7 1/4" skill saw (electric) / Milwaukee 7"/9" polisher (electric) / Craftsman X488 Router / (electric) / Makita XDT15 18V impact driver (battery) / DeWalt DC759 drill (battery) / Craftsman router (electric) / Milwaukee jig saw (electric) / DeWalt D21007 3/8 drill (electric) / Porter cable Model 314 4 1/2" trim saw (electric) / Black and Decker 3 1/4" planer (electric) / Milwaukee drill (electric) / Makita BSS611 6 1/2" skill saw (battery) / Milwaukee 1/2" drill (electric) / Milwaukee 3/8" drill (electric) / DeWalt DW936 skill saw (battery) / Black and decker drill (electric) / Black and decker 1/2"drill (electric) / Milwaukee drill (electric) / Black and decker 2670 1/2" compact wrench (electric) / Milwaukee 7 1/4" skill saw (electric) | | | | | | |
| 17 | | | | Pallet of 20 ton and 3 ton floor jack | | | | | | |
| 18 | | Craftsman | 315218060 | Craftsman 10 inch mobile table saw, 15amp motor 120V, 5000RPM | | X0535 | Black and grey | | | Works and rolls well, no blade guard |
| 19 | | | | Pallet of 22 ton and 20 ton jacks | | | | | | |
| 20 | | | | Delta sawbuck frame and trim saw SN 92J99827 | | | | | | |
| 21 | | | | (1) Pallet of small engines, winch and paint supplies | | | | | | |
| 22 | | | | Craftsman 12" band saw-sander model #113243401 SN 921100190 | | | | | | |
| 23 | | | | Buckeye Boiler Company air compressor model #50-6715 | | | | | | |
| 24 | | | | Lincoln electric AC/DC Arc Welder | | | | | | |
| 25 | | | | Campbeu Hausfeld airless paint sprayer | | | | | | |
| 26 | | | | Powermatic jointer model #50 SN 67-6688 | | | | | | |
| 27 | | | | Powermatic Model 100 planer SN 9610075 | | | | | | |
| 28 | | | | (2) Liquid tailgate tanks | | | Off white | | | |
| 29 | | | | Pallet of (8) dump body props | | | Yellow | | | |
| 30 | | | | (1) Tire chain | | | | | | |
| 31 | | | | (8) Street light bases | | | | | | |
| 32 | | | | Pallet of (3) VIKING tub body chains | | | | | | |
| 33 | | | | (1) Steel welding table | | | | | | |
| 34 | | | | (1) Wood work bench | | | | | | |
| 35 | | Norco | | (1) 20 Ton shop press model 78023 | | | Red | | | |
| 36 | | Winco | | (1) Generator fuel driven CSAPSS8B/N | | 26306 J98 | Tan | | | |
| 37 | 2017 | Chevrolet | Silverado | Automatic crew cab | 218909 | 1GCVKNEC3HZ218909 | Green | 77,894 | | Poor - needs transmission and battery. |
| 38 | 2017 | Chevrolet | 1500 | 5.3L, Auto, 4DR, 4WD, AC, Power Windows, Power door locks, | 218576 | 1GCVKNEC2HZ218576 | Green | Unknown | | Poor - Vehicle has unknown mechanical problems and no battery |
| 39 | | | | Husqvarna 7021P push mower SN 030210M-011566 | | | | | | |
| 40 | | | | Husqvarna 155BT backpack blower / John Deere BP50LE backpack blower | | | | | | |
| 41 | | | | (1) Dog kennel from a 2015 Chevrolet - Incomplete, panels only | | | | | | |
| 42 | | | 2020 | CLEMCO 150PSI Sand blaster | | 31778 | | | | |
| 43 | | | | Pak Fork tractor forks | | | | | | |
| 44 | 2023 | Chevrolet | Silverado K2500 BED ONLY | OEM Short bed only | | N/A | Orange | | | |
| 45 | 2023 | Chevrolet | Silverado K2500 BED ONLY | OEM Short bed only | | N/A | Orange | | | |
| 46 | 2023 | Chevrolet | Silverado K2500 BED ONLY | OEM Short bed only | | N/A | Orange | | | |
| 47 | 2023 | Chevrolet | Silverado K2500 BED ONLY | OEM Short bed only | | N/A | Orange | | | |
| 48 | | | | (1) Spreader bar for lifting | | | Yellow | | | |
| 49 | | | PR521 | CUB CADET - Push Mower | | 1C011K50303 | | | | |
| 50 | | Power | PSSHD26T | 212cc 26" snowblower | | | Red | | | Not currently running; needs new flywheel and other parts |
| 51 | | | SHPE2000 SERIES | Material Spreader | 2657 | | | | | |
| 52 | 2023 | Chevrolet | Silverado K2500 BED ONLY | OEM Short bed only | | N/A | Orange | | | |
| 53 | | L3 Communications | MPRI | Truck driver simulator | | | | | | |
| 54 | 2015 | Kawasaki | Mule | 4WD UTV | | | Green | | 1575 | No longer runs, no keys |
| 55 | | John Deere | X590 | X590 riding lawnmower | 110561 | 1MOX590EHGM110561 | Green | | 939 | Well used; still works; last serviced 11/2022; last used September 2023 |
| 56 | | John Deere | X590 | John Deere X590 mower, 54" deck | 122166 | 1M0X590EPHM122166 | Green | | 811 | Fair |

| LOT# | Year | Make | Model | Description | Last 6 digits of VIN # | Complete VIN# | Color | Mileage | Hours | Condition |
|------|------|-------------|--------------|---|------------------------|-----------------------------|------------------|---------|---------------|--|
| 57 | 2012 | John Deere | Ztrak 925A | Zero-turn mower with 60 inch deck | 032335 | 1TC925ACCCY032335 | Green and yellow | | 1,800 | Zero-turn mower in poor condition, motor and mechanics are disassembled with pieces and parts in separate box, body is worn due to age and use, seat in fine condition, good for parts |
| 58 | | John Deere | Z950M | John Deere Z950M zero turn mower, 60" deck | 061809 | 1TC950MCEJT061809 | | | 1198 | Fair |
| 59 | | Club Car | Golf cart | Golf cart | 038898 | AQ0931-038898 | Green | | | Still runs; steering and brakes are not very reliable and need repair |
| 60 | | | | Kay blue pedal boat SN KAX055571000 | | | | | | |
| 61 | | | | Kay green pedal boat SN KAX055521000 | | | | | | |
| 62 | | Yamaha | YDREX4 | Golf cart | YAM42 | | Green | | | No longer runs; needs new control board |
| 63 | | EZGo | TXT | Golf cart | 509025 | 2509025 | Green | | | No longer runs |
| 64 | | | | Kay yellow pedal boat SN KAX055601000 | | | | | | |
| 65 | | | | Push behind DR field and brush mower, 8HP Briggs and Stratton engine | | | | | | unknown |
| 66 | | | R270 | (3) Ground Pounders | | 2715716 / 2715160 / 2715714 | | | | |
| 67 | | | | Pelican green double kayak | | CA-ZEP65512D919 | | | | |
| 68 | | | | Fusion 124 blue kayak SN QJE11840B717 | | | | | | |
| 69 | | | | Pelican blue kayak | | CA-ZEP62391A717 | | | | |
| 70 | | | | Perception Sparky 9.5 green kayak WEMDJ216K203 | | | | | | |
| 71 | | | | Fusion 124 yellow kayak SN QJE12757C615 | | | | | | |
| 72 | | | | (2) Husqvarna 232R string trimmer / (2) Husqvarna 223L string trimmer / Husqvarna 323L string trimmer | | | | | | |
| 73 | | | | 4 Sets - Yokohama Avid S34 all season tires size 235/65/17 | | Pallet 7 | | | | |
| 74 | | | | 12' Grumman aluminum boat | | GBM15397D939 | | | | |
| 75 | | | | Canoe | | GBM79760M79K-7A | Aluminum | | | |
| 76 | | | | 12' Grumman aluminum boat | | GBMN6117E990 | | | | |
| 77 | | Paddle King | | Pedal boat | | PAB01519G911 | | | | |
| 78 | | Paddle King | | Pedal boat | | PAB01505G911 | | | | |
| 79 | 1986 | Ski-Doo | Citation | Old snowmobile | 02191 | 3210-02191 | Yellow | | | Poor condition. cracked cowell, torn seat, broken fuel tank neck, torn track, broken kill switch button. |
| 80 | 1988 | Polaris | Sprint | Old snowmobile | 517374 | 1517374 | | 2,621 | | Poor condition. Torn seat, cracked windshield, broken gas cap, bent "bumper", bent ski. |
| 81 | | Kubota | F2260 | Kubota F2260 72" front end mower, does not run, needs starter relay | 10134 | | | 1,900 | | |
| 82 | | | | (1) Pallet of tarp parts | | | | | | |
| 83 | | | | (1) Pallet of OEM various manufacturers components | | | | | | |
| 84 | | | | Pallet of international parts OEM and aftermarket | | | | | | |
| 85 | | | | Pallet of international parts OEM and aftermarket | | | | | | |
| 86 | | Atlas | | (1) Tire balancer model WB-41 | | 738683030820ER | Blue | | | Works |
| 87 | | Corgi | | (1) Tire machine model A2024 TI MA | | CDC005563 | Red | | | Works |
| 88 | | | | Misc. Core drilling bits | | | | | | |
| 89 | | | | (1) Pallet of lighting mounting hardware and lights | | | | | | |
| 90 | | | | (1) Pallet of glass for equipment | | | | | | |
| 91 | | | | (2) Pallet of Misc. Shop Compenents | | | | | | |
| 92 | | SESA | | Light Panel / Sign | | | | | | |
| 93 | 2002 | Geith | | Geith 1.25 CUYD A/TILT | 103451 | | | | | |
| 94 | | Viking | Flex Plow | POLY Reversible plow, 11' | | N/A | Black and orange | | | |
| 95 | | Viking | One-way plow | BARRELL Plow 11' | | N/A | Black | | | |
| 96 | | | | Metal Mower attachment 7.5ft. | | | Yellow | | | |
| 97 | | | | (1) Pallet of Misc. hardware / mounting blocks, etc. | | | | | | |
| 98 | | | | Wooden storage unit with Misc. electrical and plumbing parts | | | | | | |
| 99 | | Goodyear | G622-RSD | 1 Tire 255/70/R22.5 | | | | | | |
| 100 | | | | 4 Sets - Toyo Extena A/S all season tires size 195/60/17 | | Pallet 2 | | | | |
| 101 | | | | 4 Sets - Bridgestone Ecopia EP422 all season tires size 195/60/17 | | Pallet 1 | | | | |
| 102 | | | | 4 Sets - Firestone Destination LE all season size 225/65/17 | | Pallet 5 | | | | |
| 103 | | | | 2 Sets - Continental Van Contact A/S all season size 235/65/16C / 2 Sets - Bridgestone Dueler H/T all season tires size 255/70/16 | | Pallet 6 | | | | |
| 104 | | | | 4 Sets - Pirelli Scorpion ATR all season tires size 265/70/17 | | Pallet 8 | | | | |
| 105 | | | | 4 Sets - Pirelli Scorpion ATR all season tires size 265/70/17 | | Pallet 9 | | | | |
| 106 | | | | 3 Sets - Continental Pro Contact TX all season tires size 225/65/17 1 Set - Yokohama Avid S34 all season tires size 235/65/17 | | Pallet 4 | | | | |
| 107 | | | | 4 Sets - Michelin Primacy A/S all season tires size 225/65/17 | | Pallet 3 | | | | |
| 108 | 2012 | Chevrolet | Impala | Sedan - 4DR, 3.6L 6 Cyl, Automatic, Power windows and door | 221627 | 2G1WF5E34C1221627 | Silver | 142,166 | | Key turns hard, brakes rusty, surface rust on body, rusty rocker panels, Interior dirty |
| 109 | 2015 | Ford | Explorer | Interceptor - 3.7L engine, V6, AWD, automatic, Power windows, locks, and seat | B62667 | 1FM5K8AR9FGB62667 | Black | 181,873 | 4604 Idle 966 | Trans shifts hard, mode door actuator bad, Interior is dirty/worn |

| LOT# | Year | Make | Model | Description | Last 6 digits of VIN # | Complete VIN# | Color | Mileage | Hours | Condition |
|------|------|-----------|-----------------|---|------------------------|-------------------|---|---------|-------|--|
| 110 | 2016 | Chevrolet | Impala | Sedan - 4DR, 3.6L 6 Cyl, Automatic, Power windows and door | 103513 | 2G1WA5E37G1103513 | Silver | 114,017 | | Flex pipe bod, Tire light on, Rear bumper rusty, R. Wheel braking noise, body has 2 small dents. Interior is Fair |
| 111 | 2015 | Ford | Explorer | Interceptor - 3.7L engine, V6, AWD, automatic, Power windows, locks, and seat | B20510 | 1FM5K8AR8FGB20510 | Black | 153,087 | 4296 | Exhaust flex pipe bad, ABS light on, Brakes rusted, Rust on roof, Chips in hood. Interior is Fair |
| 112 | 2011 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 240150 | 1GC1KXCG0BF240150 | Black | 167,487 | | Rust holes in bed, engine issues, several dash lights on. |
| 113 | 2015 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 660353 | 1GC1KVEG0FF660353 | Grey | 154,707 | | Starts, runs and drives |
| 114 | 2015 | GMC | SIERRA K1500 | 1/2 Ton crew CAB, 4X4 | 231314 | 1GTV2UEC5FZ231314 | Black | 111,929 | | Needs transmission, exhaust, front end work |
| 115 | 2020 | Ford | F150 | Crew CAB, 4X4 | E66324 | 1FTEW1P43LKE66324 | Black | 63,437 | | Flood unit, many lights on dash |
| 116 | 2011 | Ford | F250 | 4WD AC Auto Trans 5.4L V8 Cyl Gas Tire size LT245-75-17 | C53419 | 1FT7W2B66BEC53419 | White | 45,241 | | Average - Mechanical: Vermont state inspection expires February 2025, tires are all season with 75% remaining tread, last user reported no known issues or defects, vehicle has been sitting for a few months in preparation for sale, one owner vehicle purchased new, very clean truck, selling due to normal rotation of inventory. Body: ARE DCU truck cap with ladder and pipe rack, very clean truck, no rust or damage. Interior: Interior is fairly clean, manual 4WD, manual windows, locks, mirrors |
| 117 | 2016 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 249815 | 1GC1KVEG4GF249815 | Blue | 145,670 | | Runs and drives starts |
| 118 | 2015 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 550486 | 1GC1KVEG6FF550486 | Blue | 149,426 | | Runs and starts, drives |
| 119 | 2015 | Chevrolet | Silverado K1500 | 1/2 Ton crew CAB, 4X4 | 201328 | 3GCUKREC8FG201328 | Black | 189,450 | | Starts, runs and drives |
| 120 | 2014 | Toyota | Tacoma | Toyota tacoma V6, 4 door crew cab, 4WD, automatic door locks, power windows, manual seats, truck cap included | 024203 | 5TFMU4FN2EX024203 | Gray | 153,295 | | Fair |
| 121 | 2013 | Dodge | Ram 2500 | 3/4 ton pickup truck with utility box and lumber rack, automatic transmission, 4WD, equipped with connections and bolts for Fisher V-plow | 524270 | 3C6LR5AT4DG524270 | White and green | 99,115 | | Truck in fair condition, sometimes has trouble starting, brand new battery, leaking driver side in floorboards and behind driver seat, significant rusting to undercarriage and parts of body/box, cracked windshield, wiring harness for Fisher V-plow replaced 1 year ago |
| 122 | 2015 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 660327 | 1GC1KVEGXFF660327 | Black | 175,821 | | Starts, runs and drives |
| 123 | 2008 | Ford | F450 | 1.5 Ton crew CAB, 4X4 | A85863 | 1FDXW47R28EA85863 | Blue | 132,164 | | Needs to be towed, will not start or run |
| 124 | 2015 | Chevrolet | Silverado K1500 | 1/2 Ton crew CAB, 4X4 | 464893 | 3GCUKREC5FG464893 | Dark Grey | 183,457 | | No leaks, start unassisted, engine skips |
| 125 | 2015 | Chevrolet | Silverado K3500 | 1 Ton crew CAB, 4X4 | 663603 | 1GC4KZCG2FF663603 | Blue | 148,343 | | No transmission oil, was running, no leaks |
| 126 | 2012 | Ford | F550 | 1.5 Ton crew CAB, 4X4 | A33340 | 1FD0W5HYXCEA33340 | Blue | 139,608 | | Does not start |
| 127 | 1992 | Clark | 6000 | 8,000 LB lift capacity forklift | 9215KF | Y68501059215KF | Green | | | Flood unit, worked prior to flood |
| 128 | 2015 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 661087 | 1GC1KVEGXFF661087 | Black | 121,605 | | Runs and drives. |
| 129 | 2011 | Chevrolet | Colorado | 1/2 ton pickup truck crew cab, with cap, automatic transmission, 4WD | 115661 | 1GCJTBF5B8115661 | Grey | 100,877 | | Truck in fair condition, starts and operates well, rusting of undercarriage and some rusting on body, issues with leaking water on interior on passenger side and windshield, snow tires in fair condition |
| 130 | 2016 | Ford | F250 Super Duty | 3/4 ton pickup truck with utility box and lumber rack, automatic transmission, 2WD | D01008 | 1FTBF2A63GED01008 | Dark green, Exterior Paint Code W6, black utility box | 48,912 | | Truck in fair condition, starts and operates well, some rusting on undercarriage, worn leaf springs, exhaust leak, windshield wiper control issue, front bumper replaced within past 5 years, been sitting outside past 6 months |
| 131 | 2013 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 135337 | 1GC1KXCG2DF135337 | Black | 140,427 | | Water leaks into cab, former k9 unit, missing interior components, |
| 132 | 2007 | Chevrolet | Colorado | 2-door 2WD pickup | 126377 | 1GCCS149478126377 | Green | 76,508 | | Cannot be inspected; rust on frame; broken tailgate latch |
| 133 | 2018 | Chevrolet | Silverado | Automatic crew cab 1500 PK | 163590 | 1GCVKNEC8JZ163590 | Black | 148,152 | | Fair-needs new battery |
| 134 | 2015 | Chevrolet | Silverado | 2500 HD, 6.0L engine, 8cyl, 4WD, Automatic, Heated Mirrors, Power Mirror seat window and door, | 136372 | 1GC2KVEGXFZ136372 | Green | 172,829 | 4553 | TPMS light is on, spare tire is on vehicle, tires are worn out, muffler has a hole, winch doesn't work. Rocker panels have holes, bed sides are rusty. Interior is dirty |
| 135 | 2017 | Chevrolet | Silverado | Automatic crew cab | 219075 | 1GCVKNEC7HZ219075 | Green | 121,054 | | Fair,Needs battery |
| 136 | 2017 | Chevrolet | Silverado | Automatic crew cab | 219320 | 1GCVKNEC5HZ219320 | Green | 123,684 | | Fair |
| 137 | 2015 | Chevrolet | Silverado K3500 | 1 Ton crew CAB, 4X4 | 664906 | 1GC4KZCG3FF664906 | Blue | 183,116 | | Starts and runs, noisy engine. With a plow |
| 138 | 2015 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 662932 | 1GC1KVEG4FF662932 | Blue | 166,744 | | Some rust issues, runs and drives |
| 139 | 2015 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 662258 | 1GC1KVEG5FF662258 | Blue | 150,230 | | Runs and drives |
| 140 | 2012 | Chevrolet | Silverado K2500 | 3/4 Ton single CAB, 4X4 | 113859 | 1GC0KXCG9CZ113859 | Blue | 70,381 | | Runs and starts, drives |
| 141 | 2012 | Chevrolet | Silverado K1500 | Regular CAB, 2WD | 163117 | 1GCNCSE09CZ163117 | Black | 110,061 | | Runs and drives |
| 142 | 2016 | Chevrolet | Silverado K2500 | 3/4 Ton crew CAB, 4X4 | 248620 | 1GC1KVEG6GF248620 | Blue | 220,932 | 8186 | Exhaust leaks,needs brakes, starts unassisted |
| 143 | 2013 | Chevrolet | Silverado K1500 | XTRA CAB, 4X4 | 209977 | 1GCRKSEA7DZ209977 | Teal | Unknown | | Start, runs and drives |
| 144 | 2016 | Chevrolet | Silverado | Automatic crew cab | 242188 | 1GCVKNEC5GZ242188 | Green | 63,566 | | Fair |
| 145 | 2016 | Chevrolet | Silverado | Automatic crew cab | 241905 | 1GCVKNEC2GZ241905 | Green | 104,202 | | Fair,Needs battery,some body damage |

| LOT# | Year | Make | Model | Description | Last 6 digits of VIN # | Complete VIN# | Color | Mileage | Hours | Condition |
|------|------|---------------|-----------------|--|------------------------|-------------------|------------|---------|---------|--|
| 146 | 2016 | Ford | F150 | 4WD AC Auto Trans 3.5L V6 Cyl Gas Tire size 265-70-17 | F34594 | 1FTMF1E81GKF34594 | Green | 132,009 | | Rough - Mechanical: Vermont state inspection expires September 2024, tires are all season tread with about 25% remaining, last user reported no known issues or defects, vehicle has been sitting for a few months in preparation for sale, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: Large dent in passenger side bed side, ARE color matched truck cap, windshield cracked, doors have residue from decal removal, tow receiver is suted in, dented rear bumper, paint chips, other minor scratches and dings may be found throughout. Interior: Interior is dirty and in need of cleaning, |
| 147 | 2014 | Chevrolet | Silverado | 4WD, A/C, 8 Cyl, tow hitch, power windows, power door | 338885 | 3GCUKPEC8EG338885 | Black | 124,467 | | Rocker panel rust, worn brakes, ball joints issue, A/C doesn't blow cold air |
| 148 | 2012 | Ford | E350 Cargo Van | 2WD AC Auto Trans 5.4L V8 Cyl Gas Tire size LT245-75-16 | A59299 | 1FTSS3ELXCDA59299 | Silver | 96,949 | | Average - Mechanical: Not currently state inspected at all, no sticker, no known issues or defects, vehicle has been sitting for a few months in preparation for sale, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: Front bumper rusted thorough, rust on lower rear quarter panels, rust bubbles forming on rocker panels, minor scratches and dings may be found throughout, side doors do not open. Interior: Interior is dirty and in need of cleaning, holes on interior from accessory removal. cargo van with no rear seats |
| 149 | 2017 | GMC | Sierra 1500 | 4WD AC Auto Trans 4.3L V6 Cyl Gas Tire size 265-70-17 | 131930 | 1GTN2LEH8HZ131930 | Black | 95,570 | | Average - Mechanical: Vermont state inspection expires June 2024, tires are winter tread with about 50% remaining, CEL light on, steering assist light illuminated, vehicle has been sitting for a few months in preparation for sale, one owner vehicle purchased new, selling due to normal rotation of inventory. Body: ARE color matched cap, minor scratches and dings may be found throughout. Interior: Interior is dirty, holes from accessory removal |
| 150 | 2014 | Chevrolet | Silverado K1500 | 1/2 Ton crew CAB, 4X4 | 257918 | 3GCUKREC3EG257918 | Light Blue | 162,561 | | Leaks, frame rust holes, starts unassisted |
| 151 | 2008 | Volvo | EW55B | Wheeled excavator, 10K pound with 2 buckets and thumb | B31045 | EW55B31045 | Yellow | | 4244 | Starts, runs and drives, SOME HYDRAULIC LEAKS |
| 152 | 2006 | Caterpillar | 924G | Front end loader | A03135 | DDA03135 | Yellow | | 5992 | Minor engine oil leak, minor transmission leak, parking brake does not work, battery draws, some rust |
| 153 | 2006 | Caterpillar | 924G | Front end loader | A02907 | DDA02907 | Yellow | | 5796 | Starts, runs and drives |
| 154 | 2006 | Caterpillar | 924G | Front end loader | A02914 | DDA02914 | Yellow | | 3916 | Minor fluid leaks, rust holes in cab, weak starting, rust all over, loader pins have excessive play |
| 155 | 2013 | International | 7400 | Dump truck with plow & wing | 202980 | 1HTWDAZR5DH202980 | Orange | 102,842 | 5252 | No start or crank |
| 156 | 2013 | International | 7400 | Dump truck with plow & wing | 202984 | 1HTWDAZR2DH202984 | Orange | 98,715 | 5498 | No start, needs to be towed |
| 157 | 2015 | International | 4300 | Dump truck with plow | 609896 | 1HTJTSKL8FH609896 | Orange | 96,241 | 6381 | Starts, runs and drives |
| 158 | 2014 | International | 7400 | Dump truck with plow & wing | 064771 | 1HTWDAZR4EH064771 | Orange | 107,229 | 6033 | No leaks, plow front broken, starts and runs |
| 159 | 2013 | International | 7600 | Dump truck with plow & wing | 418546 | 1HTGRSHT5DH418546 | Orange | 122,533 | 6388 | Cranks, needs to be towed |
| 160 | 2013 | International | 7600 | Dump truck with plow & wing | 418552 | 1HTGRSHT0DH418552 | Orange | 93,605 | 5064 | |
| 161 | 2013 | International | 7400 | Dump truck with plow & wing | 202979 | 1HTWDAZR9DH202979 | Orange | 78,254 | 5253 | Engine has blow by, starts unassisted |
| 162 | 2012 | International | 7400 | Dump truck with plow & wing | 536121 | 1HTWDAZR6CJ536121 | Orange | 99,285 | 4997 | No leaks, starts and runs |
| 163 | 2012 | International | 7600 | Dump truck with plow & wing | 536937 | 1HTGRSHT8CJ536937 | Orange | 114,909 | 5395 | Needs engine work, needs hoist cyl, hydraulic leaks, rust |
| 164 | 2013 | International | 7600 | Dump truck with plow & wing | 418543 | 1HTGRSHT9DJ418543 | Orange | Unknown | Unknown | Poor engine condition, needs fuel pump, minor rust, air leak, torque rod bushing no good |
| 165 | 2015 | International | 2400 | 2WD, Liftgate Automatic 6 Wheel Automatic AM/FM RadioManual windows Maxforce 9 330HP 17' Box | 514504 | 1HTWCAZNFH514504 | Blue | 230,879 | 6054 | Good (needs Inspecton) |
| 166 | 2013 | International | 7600 | Dump truck with plow | 418544 | 1HTGRSHT0DJ418544 | Orange | | | |
| 167 | 2012 | International | 7400 | Dump truck with plow & wing | 536119 | 1HTWDAZR8CJ536119 | Orange | 120,081 | 6225 | Oil leak on passanger side of block, some rust |
| 168 | 2008 | International | 7500 | Dump truck with plow & wing | 696914 | 1HTWDAZR88J696914 | Orange | 84,750 | 5030 | Some fluid leaks, some air leaks, good engine. |
| 169 | 2011 | International | 7400 | Dump Truck | 409774 | 1HTWEAAR9BJ409774 | Red | 22,486 | 2976 | Fair |
| 170 | 2008 | Wells Cargo | EW2425W | | 071531 | 1WC200L2994071531 | | | | |
| 171 | 2002 | Evaco | D020T282TA | 20 Ton trailer, tilt deck | 283209 | 1E9DE28221A283209 | Yellow | n/a | n/a | |
| 172 | 2002 | Evaco | D020T282TA | 20 Ton tailer, tilt deck | 283214 | 1E9DE28261A283214 | Yellow | n/a | n/a | Frame needs repair, needs new brakes, needs new wiring. |
| 173 | 1989 | Capital | EC14 | Utility equipment trailer, tandem axle, GAWR 8000, carrying capacity 8000, GVWR 9650, s/n 757DX, not certified for highway use | 193757 | 1C9EC2028K1193757 | Yellow | | | Old trailer with some rusting, unknown brake condition, overall works well |
| 174 | 2000 | Walker | Tanker | SS 7,000 Gallon water tank | 033740 | 5WSAA4520YN033740 | Silver | n/a | n/a | |
| 175 | 2019 | International | HV513 | Dump truck with plow & wing | 071684 | 1HTEMZT2KH071684 | Orange | 497,61 | 2631 | Truck caught fire, does not run, forward of body in great shape |